Tether equilibrium and material sensitivity

Earth · radial, constant-stress reference without payload or distributed hardware





The lab value is measured ultimate tenacity. The design curve requires an allowable.